



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Respirator disposable face mask

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
KN95 protective respiratory filtration half-face mask.

Packaging description
The product is wrapped individually in a plastic bag and packaged in a white cardboard box containing 40 pieces.

Product Recall

Type/number of model
• **non for medical**

Batch number
• **Production batch: DY2020Y05M**
• **Production date: 2020.5.8**

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01057/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The particle/filter retention of the material is insufficient (measured value 89 %) and the mask does not properly adapt to the face. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply
The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Marking the product with appropriate warnings on the risks
09/06/2020

Year

Country of origin

Alert submitted by





Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
FFP2 face mask

Brand (on the product or the packaging)
• **Bonway**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
KN95 protective respiratory filtration half-face mask of category FFP2 according to EN 149.

Packaging description
The product is wrapped individually in a plastic bag and packaged in a white and blue cardboard box containing 20 pieces.

Product Recall

Type/number of model
• **134949**

Batch number
• **20200408**

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01061/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. Additionally, the total filtration capacity of the mask is insufficient (measured mean value 79 %).

Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

**Import rejected at border
06/05/2020**

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
KN95 protective mask

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
KN95 protective respiratory filtration half-face mask, corresponding to FFP2 according to EN 149.

Packaging description
The product is wrapped in pairs in a plastic bag and packaged in a white and red cardboard box containing a total of 20 pieces.

Product Recall

Type/number of model
Unknown

Batch number
• **20200418**
• **Date of Manufacture: 2020/04/08**

Bar code
• **6 973187 900101**

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01062/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The particle/filter retention of the material is insufficient (measured value 84 %) Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Marking the product with appropriate warnings on the risks

Year

Country of origin

Alert submitted by





Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Three-dimensional protective respirator

Brand (on the product or the packaging)
• VHC Global

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
KN95 protective respiratory filtration half-face mask of category FFP2 according to EN 149.

Packaging description
The product is wrapped individually in a plastic bag and sold in a white cardboard box containing 40 pieces.

Product Recall

Type/number of model
• KN95

Batch number
• 20200420

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01072/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. Additionally, the particle/filter retention of the material is insufficient (measured value 93 %) and the mask does not properly adapt to the face, leading to an insufficient total filtration capacity (measured mean value 89 %). Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
27/05/2020

Year

Country of origin

Alert submitted by





Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Máscara facial

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Respiratory filtration half-face mask.

Packaging description
The product is sold in a white and blue cardboard box containing 50 units.

Product Recall

Type/number of model
Unknown

Batch number

- **Production number: 20200423**
- **Production Date: 2020-4-27**

Bar code

- **2 100128 289597**

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01073/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)
The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply
The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Marking the product with appropriate warnings on the risks
08/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Civil use disposable face mask

Brand (on the product or the packaging)
• 3 PLY

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Respiratory filtration half-face mask.

Packaging description
The product is sold in a white and blue cardboard box containing 50 pieces.

Product Recall

Type/number of model
• BFE > 90 %

Batch number
• Production Date: 2020-04-23
• Production number: 200423

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01074/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply
The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
05/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable face mask / Disposable protective mask (three layers)

Brand (on the product or the packaging)
• Non-woven.com

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Respiratory filtration half-face mask.

Packaging description
The product is sold in a white, yellow and blue cardboard box containing 50 pieces.

Product Recall

Type/number of model
• Model NO.: D22-1

Batch number
• Production date: Apr.19.2020
• L/N: 20200419

Bar code
• 6 973162 200073

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01075/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
08/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Non medical Disposable Mask

Brand (on the product or the packaging)
• **X.Y.T. Xiang Yan Tang**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Respiratory filtration half-face mask.

Packaging description
The product is sold in a white and blue cardboard box containing 50 pieces.

Product Recall

Type/number of model
Unknown

Batch number
Unknown

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01076/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
29/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Protective Face Mask

Brand (on the product or the packaging)
• **PM Plus Medical**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
Unknown - No information available

Professional product?
No

Product description
Protective respiratory filtration half-face mask of category FFP2 according to EN 149.

Packaging description
The product is wrapped in sets of 10 units in a plastic bag with zip closure and packaged in a cardboard box containing 5 sets.

Product Recall

Type/number of model
Unknown

Batch number
• **Manufacturing date: 2020-04-09**

Bar code
Unknown

Is the product counterfeit?
Unknown

Is this notification linked to a Business Gateway case?

Case number
A12/01080/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The particle/filter retention of the material is insufficient (measured value 90.5 %) Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation and the relevant European standard EN 149.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Distributor

Ban on the marketing of the product and any accompanying measures





Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable face mask

Brand (on the product or the packaging)
• **Fitme**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask

Packaging description
The product is sold in a white and blue cardboard box containing 50 pieces.

Product Recall

Type/number of model
• **KTM001**

Batch number
• **KTMFM20200425**
• **Manufacture date: 25/04/2020**

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01094/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Marking the product with appropriate warnings on the risks
25/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable protective mask

Brand (on the product or the packaging)
• **Owoge**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask.

Packaging description
The product is sold in a white cardboard box containing 50 pieces.

Product Recall

Type/number of model
Unknown

Batch number
• **2020-04-14-012**

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01098/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

**Import rejected at border
19/05/2020**

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable face mask

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask

Packaging description
The product is sold in a white and green cardboard box containing 50 pieces.

Product Recall

Type/number of model
Unknown

Batch number
• 2020-04-12-012

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01099/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Import rejected at border
19/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Facemask - disposable non-medical protective mask

Brand (on the product or the packaging)
Care U

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask according to EN 149.

Packaging description
The product is sold in a white and grey cardboard box containing 50 pieces.

Product Recall

Type/number of model
• 0H200321S.WLT 0133

Batch number
• April 2020

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01101/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply
The product does not comply with the Personal Protective Equipment Regulation and the relevant European standard EN 149.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Import rejected at border 19/05/2020

Year

Country of origin

Alert submitted by

DRAFT



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable face mask

Brand (on the product or the packaging)
• **YBW**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask.

Packaging description
The product is sold in a grey cardboard box containing 50 pieces.

Product Recall

Type/number of model
Unknown

Batch number
• **91361027MA395**
A8X6T
• **16679066288**

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01102/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply
The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

Import rejected at border
19/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable protective mask

Brand (on the product or the packaging)
• **Runbo**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask.

Packaging description
The product is sold in a white and red cardboard box containing 50 pieces.

Product Recall

Type/number of model
• **AKF2001**

Batch number
• **200503A01**

Bar code
• **6973250740016**

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01108/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
26/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable protective civilian mask

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask.

Packaging description
The product is sold in a white and blue cardboard box containing 50 pieces.

Product Recall

Type/number of model
• **KZ-001**

Batch number
Unknown

Bar code
• **4895076518872**

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01109/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
18/05/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable face mask

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask.

Packaging description
The product is sold in a white and blue cardboard box containing 50 pieces.

Product Recall

Type/number of model
Unknown

Batch number
Unknown

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01115/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

**Import rejected at border
19/05/2020**

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Disposable face masks

Brand (on the product or the packaging)
Unknown

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
Protective respiratory filtration half-face mask.

Packaging description
The product is sold in a white and green cardboard box containing 50 pieces.

Product Recall

Type/number of model
Unknown

Batch number
• LLK20200408

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01116/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The product bears a CE marking but is not certified as protective equipment by a relevant body. The visual inspection of the product reveals that its material composition, structure and shape are inappropriate. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply

The product does not comply with the Personal Protective Equipment Regulation and with the relevant European standard EN 149.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Other

**Import rejected at border
19/05/2020**

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium



Product (what the product is)
Particle filter mask

Name (on the product or the packaging)
Respirator 9591

Brand (on the product or the packaging)
• **Allta**

OECD Portal category (if known)
85000000 - Safety / Protection - DIY

Is the product (also) sold online?
No

Professional product?
No

Product description
KN95 protective respiratory filtration half-face mask.

Packaging description
The product is wrapped in a transparent plastic blister containing 5 pieces.

Product Recall

Type/number of model
• **9591**
• **KN95**

Batch number
• **Product Batch: 152020**
• **Production Date: 2020/4/16**
• **Expiration Date: 2023-04-15**

Bar code
Unknown

Is the product counterfeit?
No

Is this notification linked to a Business Gateway case?

Case number
A12/01060/20

Type of risk
Health risk / other

Risk description (technical defect and consequences)

The mask does not properly adapt to the face. Consequently, an excessive amount of particles or microorganisms might pass through the mask, increasing the risk of infection if not combined with additional protective measures.

Legal provisions (at EU level) and European standards against which the product was tested and did not comply
The product does not comply with the Personal Protective Equipment Regulation.

(Overall) risk level
Serious

Product category
Protective equipment

Measures

Compulsory measures

Importer

Marking the product with appropriate warnings on the risks
25/06/2020

Year

Country of origin

Alert submitted by

2020

People's Republic of China

Belgium